

<b>WEEKLY QUALITY ASSURANCE REPORT</b>		PAGE ____								
OF ____										
Name of Contractor: Global Engineering		Project Name: Life Safety--Walls Phase 2								
Installation Name: Fort Gordon, GA, USA		Contract/DO/PO Number: 24-128								
Contract Number: DACA01-98-D-0024		Date: week ending November 09, 2000								
(USE SEPARATE REPORT FOR Each D.O./P.O. / Contract) <b>General Comments:</b>  Started work on the 11 <sup>th</sup> floor.										
<b>Work performed:</b>  Painted existing ceiling grid. Removed old ceiling tile. Installed new ceiling tiles. Relocated exit lights that were mounted in a wall. Moved them to a ceiling location. Patched holes. Tied exit lights into hospital life safety power.										
Percent complete (if applicable) <u>  20  </u> % .										
<b>Safety violations / Corrective measures taken:</b> Safety meeting held										
<b>Work Scheduled:</b>										
<b>Indicate Attachments:</b> <table style="width: 100%; border: none;"> <tr> <td style="width: 25%;">% Daily QA Reports</td> <td style="width: 25%;">% Schedule assessments</td> <td style="width: 25%;">% Inspection Checklist</td> <td style="width: 25%;">% Other</td> </tr> <tr> <td>% Safety Tool Box Meeting</td> <td>% Minutes of Meetings</td> <td colspan="2">% Assistance provided to Facility</td> </tr> </table> Manager			% Daily QA Reports	% Schedule assessments	% Inspection Checklist	% Other	% Safety Tool Box Meeting	% Minutes of Meetings	% Assistance provided to Facility	
% Daily QA Reports	% Schedule assessments	% Inspection Checklist	% Other							
% Safety Tool Box Meeting	% Minutes of Meetings	% Assistance provided to Facility								

  

Name: <span style="color: red;">Lloyd South</span>	
(Printed) US Army Corps of Engineers Quality Assurance Representative Supporting MedCom	Signature: <span style="color: blue;">Lloyd South</span>